




MITRE GUIDES



SJA '1'



SJA '2'



SJA '3'



SJA '4'




SJA '5'




SJA '6'


ALL ABOVE ARE CUT IN 'H' POSITION




SJA 'A'



SJA 'B'



SJA 'C'



SJA 'D'

ALL ABOVE ARE CUT IN 'I' POSITION

**TO AVOID MISINTERPRETATION PLEASE
SUPPLY DRAWING**

